

DIRECTORATE OF FACTORIES AND BOILERS: ODISHA: BHUBANESWAR: 751001

No. VIE (a)-26/17 768 /Dated, the

PH: NO: 2396070

02/02/2018

To

M/s. S.N.S Erectors (P) Ltd,
At/Po- Jagannathpur, Dist- Angul.


Sub: Recognition as Boiler Repairer.

Ref:- This office Memo No. 8517 dated, 22.11.2017.

Sir,

Enclosed, please, find herewith the Boiler Repairer certificate No. 09 dated, 02.02.2018 having recognition as Class-I category of Repair^{er} (Pressure to 125 kg/cm²) for the State of Odisha, receipt of which please acknowledge.

Yours faithfully,


Director of Factories and Boilers,
Odisha, I/c

Memo No. _____ /Dated, the

Copy to all Asst. Director of Factories and Boilers I/c Zones/ Deputy Director of Factories and Boilers, I/C of Divisions for information and necessary action.


Director of Factories and Boilers,
Odisha, I/c


Ds/Dt. 02.02.2018.

2/2/18

FORM NO. 'F'
[See Rule 7 A (iii)]

No.

09

(BLR.)

Date: 2-2-2018
Bhubaneswar

CERTIFICATE OF RECOGNITION AS BOILER REPAIRER

M/S. S. N. S. ERECTORS PRIVATE LIMITED, AT/PO:- JAGANNATHPUR,
VIA:- CHAINPAL, TALCHER, DIST.:- ANGUL - 759104 are hereby recognized
as **BOILER REPAIRER** in the State of Odisha for carrying out repair of pressure parts of Boilers
coming under the purview of Indian Boiler Regulations, 1950 to be individually approved in each
case upon application from the owner of the Boiler as and when so entrusted subject to the
conditions mentioned herein.



Category of Repairer : Class -I (Pressure up to 125 Kg/Cm²)

Name of Engineer : Mr. Pradyumna Kumar Dhar,
B. Tech. (Mechanical)



Engineer :- Mr. Pradyumna Kumar Dhar

Welder:- Mr. Biswajit Bhutia

This certificate shall remain valid from 2-2-2018 to 1-2-2020

Dated at Bhubaneswar this 2nd day of February, 2018

Seal

Revalidation Details

Director of Factories & Boilers
Chief Inspector of Boilers
ODISHA

From

To

Signature of Authority

CONDITIONS

01. Prior approval / sanction of the Chief Inspector of Boilers shall be obtained before undertaking work, as required under Boilers Act, 1923 & Regulation made there under.
02. Written information should be given to the Zone Inspector, Deputy Chief Inspector and Chief Inspector of commencement and on completion of each work.
03. All work shall be offered for stage inspection to the Zone Inspector and clearance obtained from him.
04. The work undertaken under this recognition shall be done strictly in accordance with the provisions of the Indian Boiler Regulations, 1950.
05. Materials used should comply with the provisions of the Indian Boiler Regulations, 1950.
06. Welding on pressure parts shall be done by qualified welders possessing valid certificate issued under the Indian Boiler Regulations, 1950. If the validity of the welder's certificate is not renewed or rectified, the recognition shall stand cancelled to the appropriate extent.
07. The records of work undertaken and personnel engaged shall be maintained in a register.
08. The erector shall keep in his permanent employment experienced supervisor, operators, fitter and welders having competency to perform boiler erection and shall report to Chief Inspector of Boilers in case of any change as early as possible.
09. The recognition shall be renewed every two years and application shall be submitted one month before the date of expiry of the validity detailing his equipments, personnel and the list of work done.
10. This recognition is subject to constant review and is liable for cancellation if deficiencies of any nature come to notice at any point of time.